

KOD	NUMER ADAPTERA	OZNACZENIE SKRZYNI	Liczba elementów
A01 	201020047	A960E	1
A02 	201020073	CVT01 (7 biegowa)	1
A03 	303220019	6T40/6T45E/4T 60	1
A04 	201020053	A760/A761/A96 0	2
A05 	303220018	AV55-50SN	1
A07 	201020079	CVT01 (8 biegowa)	1

<p>A08</p> 	<p>201020108</p>	<p>TF-815C</p>	<p>1</p>
<p>A09</p> 	<p>201020109</p>	<p>ZF6HP19/21</p>	<p>1</p>
<p>A10</p> 	<p>201020110</p>	<p>ZF6HP26/28</p>	<p>1</p>
<p>A11</p> 	<p>201020111</p>	<p>ZF-6HP9/21/24/26/28</p>	<p>1</p>
<p>A12</p> 	<p>201020144</p>	<p>AL4</p>	<p>1</p>
<p>A13</p> 	<p>201020151</p>	<p>TF-80SC</p>	<p>1</p>
<p>A14</p> 	<p>201020152</p>	<p>TF-80SC</p>	<p>1</p>





<p>A15</p> 	<p>201020143</p>	<p>4-biegowa skrzynia</p>	<p>1</p>
<p>A16</p> 	<p>201020207</p>	<p>TF-61SN</p>	<p>1</p>
<p>A17</p> 	<p>201020212</p>	<p>TF-60SN</p>	<p>1</p>
<p>A18</p> 	<p>201020216</p>	<p>01M</p>	<p>1</p>
<p>A19</p> 	<p>201020214</p>	<p>TF-60SN</p>	<p>1</p>
<p>A20</p> 	<p>201020193</p>	<p>RE0F01/06A</p>	<p>1</p>
<p>A21</p> 	<p>201020194</p>	<p>JF011E/RE0F0A</p>	<p>1</p>

<p>A22</p> 	<p>201020213</p>	<p>K110</p>	<p>1</p>
<p>A23</p> 	<p>201020195</p>	<p>CN1A</p>	<p>1</p>
<p>A24</p> 	<p>201020209</p>	<p>722.9 - ML</p>	<p>1</p>
<p>A25</p> 	<p>201020215</p>	<p>5-biegowa skrzynia</p>	<p>1</p>
<p>A26</p> 	<p>201020220</p>	<p>09M</p>	<p>1</p>
<p>A27</p> 	<p>201020221</p>	<p>TR-60SN</p>	<p>1</p>
<p>A28</p> 	<p>201020222</p>	<p>722.9 E-klasa</p>	<p>1</p>








<p>A29</p> 	<p>201020225</p>	<p>OC8/TR-80SD</p>	<p>1</p>
<p>A30</p> 	<p>201020226</p>	<p>ZF8HP45/70/90</p>	<p>1</p>
<p>A31</p> 	<p>201020227</p>	<p>6HP-24</p>	<p>1</p>
<p>A32</p> 	<p>201020235</p>	<p>BMW , 6HP</p>	<p>1</p>
<p>A33</p> 	<p>201020238</p>	<p>OAW</p>	<p>1</p>
<p>A34</p> 	<p>201020240</p>	<p>JF011E/REOF10/1 1A</p>	<p>1</p>
<p>A35</p> 	<p>201020241</p>	<p>09G</p>	<p>1</p>








<p>A36</p> 	<p>201020245</p>	<p>9HP-28</p>	<p>1</p>
<p>A37</p> 	<p>201020247</p>	<p>6AT</p>	<p>1</p>
<p>A38</p> 	<p>201020249</p>	<p>DQ250</p>	<p>1</p>
<p>A39</p> 	<p>201020250</p>	<p>ZF8HP55</p>	<p>1</p>
<p>A40</p> 	<p>201020251</p>	<p>Mercedes 5-biegowa</p>	<p>1</p>
<p>A41</p> 	<p>201020259</p>	<p>K310</p>	<p>1</p>
<p>A42</p> 	<p>201020260</p>	<p>01J</p>	<p>1</p>

<p>A43</p> 	<p>201020279</p>	<p>5L40E</p>	<p>1</p>
<p>A44</p> 	<p>201020280</p>	<p>Citroen 1.6 THP 6-biegowa</p>	<p>1</p>
<p>A45</p> 	<p>201020281</p>	<p>CV6P</p>	<p>1</p>
<p>A46</p> 	<p>201020282</p>	<p>6F35/50</p>	<p>1</p>
<p>A47</p> 	<p>201020283</p>	<p>TG-81SC</p>	<p>1</p>
<p>A48</p> 	<p>201020284</p>	<p>6HP-26</p>	<p>1</p>
<p>A49</p> 	<p>201020285</p>	<p>DQ450</p>	<p>1</p>



<p>A50</p> 	<p>201020286</p>	<p>DSL-6AT400</p>	<p>1</p>
<p>A51</p> 	<p>201020287</p>	<p>CV6P-7000-B</p>	<p>1</p>
<p>A52</p> 	<p>201020288</p>	<p>TF-81SC</p>	<p>1</p>
<p>A53</p> 	<p>201020289</p>	<p>CN1A</p>	<p>1</p>
<p>A54</p> 	<p>201020290</p>	<p>AA81E</p>	<p>1</p>
<p>A55</p> 	<p>201020291</p>	<p>GM6L45E</p>	<p>1</p>
<p>A56</p> 	<p>201020292</p>	<p>09G</p>	<p>1</p>

<p>A57</p> 	<p>201020293</p>	<p>09G</p>	<p>1</p>
<p>A58</p> 	<p>201020294</p>	<p>Volvo</p>	<p>1</p>
<p>A59</p> 	<p>201020295</p>	<p>Dwusprzęgłowa skrzynia Mercedes</p>	<p>1</p>
<p>A60</p> 	<p>201020296</p>	<p>CVT</p>	<p>1</p>
<p>A61</p> 	<p>202020291</p>	<p>6T40 45E 6T70E 6T75</p>	<p>2</p>
<p>A62</p> 	<p>201020298</p>	<p>Skrzynia BMW</p>	<p>1</p>
<p>A63</p> 	<p>201020299</p>	<p>A760E</p>	<p>1</p>

<p>A64</p> 	<p>201020300</p>	<p>6T40E 6T45E</p>	<p>1</p>
<p>A65</p> 	<p>201020301</p>	<p>SR8AT-300</p>	<p>1</p>
<p>A66</p> 	<p>201020302</p>	<p>ZF8HP75, ZF8HP70</p>	<p>1</p>
<p>A67</p> 	<p>201020303</p>	<p>JF015E</p>	<p>1</p>
<p>A68</p> 	<p>201020304</p>		<p>1</p>
<p>A69</p> 	<p>201020305</p>	<p>6DCT450</p>	<p>1</p>
<p>A70</p> 	<p>201020306</p>	<p>722.6</p>	<p>1</p>

<p>A71</p> 	<p>201020307</p>	<p>ZF6HP-19/21</p>	<p>1</p>
<p>A72</p> 	<p>201020308</p>	<p>ZFP45/70/90</p>	<p>1</p>
<p>A73</p> 	<p>201020309</p>	<p>09G</p>	<p>1</p>
<p>A74</p> 	<p>201020310</p>	<p>DSG8</p>	<p>1</p>
<p>A75</p> 	<p>201020311</p>	<p>4F27F</p>	<p>1</p>
<p>A76</p> 	<p>201020312</p>	<p>6R80E</p>	<p>1</p>
<p>A77</p> 	<p>201020313</p>	<p>8HP</p>	<p>1</p>

<p>A78</p> 	<p>201020314</p>	<p>724.0(7G-DCT)</p>	<p>1</p>
<p>A79</p> 	<p>201020315</p>	<p>6HP-28</p>	<p>1</p>
<p>A80</p> 	<p>201020316</p>	<p>A09M</p>	<p>1</p>
<p>A81</p> 	<p>201020317</p>	<p>ZF 6HP26</p>	<p>1</p>
<p>A82</p> 	<p>201020318</p>	<p>Trumpchi GS8</p>	<p>1</p>
<p>A83</p> 	<p>201020319</p>	<p>OAW</p>	<p>1</p>
<p>A84</p> 	<p>201020320</p>	<p>09G</p>	<p>1</p>

A85 	201020321	5L40/50E	1
A86 	201020322	OBT	1